



11/6/2020 7:46:54 PM

Channel	Name	Span	Value	Min	Max	Average	$\sigma$
A	AC RMS	Whole trace	207.8 V	0 V	0 V	0 V	0 V
B	AC RMS	Whole trace	174.8 V	0 V	0 V	0 V	0 V
C	AC RMS	Between rulers	Not enough data	0 A	0 A	0 A	0 A

This glitch is intermittent. In this capture only one compressor and the pump were running, but I've successfully had both compressors running moments before this glitch ( started sequentially not simultaneously ). The compressor starting current of 27A is within rated amount of 32A.