



11/6/2020 7:46:54 PM

Channel	Name	Span	Value	Min	Max	Average	$\sigma$
A	AC RMS	Whole trace	207.8 V	0 V	0 V	0 V	0 V
B	AC RMS	Whole trace	174.8 V	0 V	0 V	0 V	0 V
C	AC RMS	Between rulers	27.05 A	0 A	0 A	0 A	0 A

	1	2	$\Delta$	1/ $\Delta$
Time Axis	-64.62 ms	-9.569 ms	55.05 ms	18.17 Hz

This glitch is intermittent. In this capture only one compressor and the pump were running, but I've successfully had both compressors running moments before this glitch ( started sequentially not simultaneously ). The compressor starting current of 27A is within rated amount of 32A.